Enrollment No: Seat No: \_

## PARUL UNIVERSITY

## **FACULTY OF ENGINEERING & TECHNOLOGY**

**B.Tech. Summer 2018 - 19 Examination** 

Semester: 3 Date: 28/05/2019

| Subject Code: 03109203 Time: 02:00pm<br>Subject Name: Manufacturing Processes Total Marks: 0 |   | _      |  |
|--|---|--------|--|
|  | tructions:  |        |  |
|  | All questions are compulsory. Figures to the right indicate full marks.   |        |  |
|  | Make suitable assumptions wherever necessary.   |        |  |
|  | start new question on new page.   |        |  |
| 0.1  | <b>Objective Type Questions</b> - (Fill in the blanks, one word answer, MCQ-not more than Five in case  | e (15) |  |
| <b>~</b> ·-  | of MCQ) (All are compulsory) (Each of one mark)   | (_0,   |  |
|  | 1. Segmental chips are formed during machining  |        |  |
|  | (A) Cast Iron (B) Mild Steel (C) High Speed Steel (D) High Carbon Steel   |        |  |
|  | 2. The main purpose of a boring operation, as compared to drilling, is to   |        |  |
|  | (A) Drill a hole (B) finish the drilled hole (C) correct the hole (D) Enlarge the existing hole   |        |  |
|  | 3. Table containsslots.   |        |  |
|  | a. T- slots b. L- slots c. H-slots d. All of these  |        |  |
|  | 4. A twist drill is a   |        |  |
|  | (A) Side Cutting Tool (B) End Cutting Tool (C) Front Cutting Tool (D) None  |        |  |
|  | 5 In Shaper machine, the ram speed of return stroke is a. slow b. equal to forward stroke c. quick d. all of the above                                |        |  |
|  | 1   |        |  |
|  | <ul><li>6 process squeezes metals into peaks and troughs with plastic deformation.</li><li>7. The centre lathes receive their power through</li></ul> |        |  |
|  |   |        |  |
|  | <ul><li>8. Lathe bed is made ofmaterial.</li><li>9. The process of beveling sharp ends of a work piece is called as</li></ul>                         |        |  |
|  | 10. The angle between the face and flank of the single point cutting tool is known as   |        |  |
|  | 11. Internal gears can be made by   | -·     |  |
|  | 12. The lead screw of a lathe hasthreads.   |        |  |
|  | 13. The depth of cut in drilling is one half the drill diameter. True or false ?  |        |  |
|  | 14. The cutting tool in a milling machine is mounted on knee . True or false ?  |        |  |
|  | 15. The Lip angle of a single point cutting tool is usually 60° to 80°. True or false?  |        |  |
| Q.2  | Answer the following questions. (Attempt any three)   | (15)   |  |
|  | A) Explain working of hydraulic shaper with neat sketch.  |        |  |
|  | B) Write short note on: Casting Defects.  |        |  |
|  | C) Explain with neat sketch up milling and down milling process. Describe its advantages and  |        |  |
|  | limitations. D) Explain Radial drilling machine with neat sketch.   |        |  |
| 03   | A) Write specification of centre lathe & Draw neat sketch of center or engine lathe.  | (07)   |  |
| Q.J  | 11) white specification of centre fathe & Draw heat sketch of center of engine fathe.   | (07)   |  |

B) Write various taper turning methods & explain any one and Write the difference between Capstan (08)& turret lathe.

B) Write the factors to be considered for selection of the grinding wheels & Explain working of (08)cylindrical grinding machine

**Q.4** A) What is pattern? Explain Any five types of patterns with neat sketch. (07)

OR

OR

A) Classify the types of foundry furnaces. Describe cupola furnace with neat Sketch.

(08)

B) In a turning operation, the following tool life was given At a cutting speed= 25 m/min, feed= 0.2 mm/rev and depth of cut = 3 mm, the tool life was one hour.  $VT^{0.12} f^{0.7} d^{0.3} = C$  Calculate the tool life if the cutting speed, feed and depth of cut are increased by 20 % individually and collectively.

(07)